

PasTime TRAX Fast-Track Installation Guide



Potential Installation Locations

PasTime recommends installing the TRAX as high in the dash as possible to ensure the best performance and to help prevent tampering.

- Above or behind instrument cluster
- Above any accessible air vents
- Above or behind the radio

**For additional install locations, contact PasTime Support at 1-800-865-3260*




When mounting the Trax device, the LED's *must* be facing up and the device should not be obstructed by metal.

TRAX Wiring Diagram



After you have found a suitable place to mount the device you will want to cut your excess wire and make the necessary electrical connections to power the unit.

As seen in the wiring diagram to the left, you will only be using the Red and Black wires. PasTime recommends making your connections with the Posi-Tap connectors seen below the wiring diagram.




- **Ground**— Pin 4 on the OBDII plug harness is a common ground and can be used for this.
- **12V Constant**— Pin 16 on OBDII plug harness is a constant power source and can be used for this.

In the picture below we can see that the OBDII plug has been unmounted to access the wires on the back of the connector.



In this picture we can see that the 12V and Ground connections have been made using the recommended Posi-Tap connectors.



If you have any questions or concerns please contact PasTime at 1-800-865-3260